Inspection Report

Name of Work	: Emergency Works (Construction of Culverts and other Works) in Ward No. 09, Vidyaranyapura Sub Division.
Work Order	: EE/BTP/BBMP/E-Proc/08(14245)/WO/330/2014-15 Dated: 25.02.2015.
Agency	: Sri K.V. Subba Reddy
B.R. No & Date	: 154/15-16 Dated: 31.08.2015
Bill Amount	: 12,79,061.80
Job Code	: 009-15-000020
P. Code	: P-1771
Date of Inspection	: 22-02-2016

The above said works (construction of culverts and other works) in ward no 09, Vidyaranyapura Sub Div was shown to me by the Concerned AE Sri Suresh.

The above work was inspected by me along with the Concerned A.E. Sri Suresh.

The measurements at selected places were verified and found satisfactory

The work done is satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: Emergency works (Construction of Culverts and other Works) in Ward No. 09 of Vidyaranyapura Sub Division.



Assistant Engineer
WardNo. 09

"Verified"

Photos for the Work of Emergency Works (Construction of Culverts and other Works) in Ward No. 09, Vidyaranyapura Sub Division.

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Emergency Works (Construction of Culverts and other Works) in Ward No. 09, Vidyaranyapura Sub Division.

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Emergency Works (Construction of Culverts and other Works) in Ward No. 09, Vidyaranyapura Sub Division.



MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Emergency Works (Construction of Culverts and other Works) in Ward No. 09, Vidyaranyapura Sub Division.

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Emergency Works (Construction of Culverts and other Works) in Ward No. 09, Vidyaranyapura Sub Division.

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Emergency Works (Construction of Culverts and other Works) in Ward No. 09, Vidyaranyapura Sub Division.

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Emergency Works (Construction of Culverts and other Works) in Ward No. 09, Vidyaranyapura Sub Division.

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Emergency Works (Construction of Culverts and other Works) in Ward No. 09, Vidyaranyapura Sub Division.

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Emergency Works (Construction of Culverts and other Works) in Ward No. 09, Vidyaranyapura Sub Division.

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Emergency Works (Construction of Culverts and other Works) in Ward No. 09, Vidyaranyapura Sub Division.

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Emergency Works (Construction of Culverts and other Works) in Ward No. 09, Vidyaranyapura Sub Division.

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Emergency Works (Construction of Culverts and other Works) in Ward No. 09, Vidyaranyapura Sub Division.



MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT